TUV Rheinland of North America, Inc.
TCB Program
Youngsville, NC 27596

TÜVRheinland®
Precisely Right.

Telecommunications Certification Body Certificate

United States of America

Equipment Certification under

47 CFR Part 68

TIA-968-A + TIA-968-A-1 + TIA-968-A-2 + TIA-968-A-3 + TIA-968-A-4 and TIA-1096

Connection of Terminal Equipment to the Telephone Network

Subject to the provisions of 47 CFR Part 68 rules and regulations, certification is hereby granted for the equipment listed below. Changes in model number(s) or trade name(s) or modifications to the network interface require amendment of certification. Each piece of equipment bearing the listed trade name(s) and model number(s) shall be labeled in accordance with the provisions of TIA/EIA/TSB168-A.

Telephone equipment containing radio-frequency circuitry may require additional authorization(s) to be issued by the Federal Communications Commission or designated TCB prior to marketing such equipment in the United States. Failure to obtain the required equipment authorizations may subject the registrant to fines and penalties provided for in table V, section 501 and 503 of the Communications Act of 1934, as amended.

Certification No.: US: 6NHMM00BR16300 **TUVRheinland File:** 30762847.001

Date Approved: October 31, 2007
Registrant: Philips France / Homes Networks – Set Top Boxes, 51 rue Carnot, Suresnes, 92156, France
Manufacturer Name: Various, Mexico
Equipment Description: Satellite Receiver with embedded analog modem
Nature of Application: Original
AC-REN: 00B
Connectors: RJ-11

Type of Equipment: Modem

Trade Name(s):	Model Number(s):	Certificates Affected:
DIRECTV	R16, R16-300, R16Y, R16YY, R16YYY, R16YYYY, R16YYYYY, R16YYYYYY, R16YYYYYYY, R16-Y, R16-YY, R16-YYY, R16-YYYY, R16-YYYYY, R16-YYYYYY, R16-YYYYYYY, LR16, LR16-300, LR16Y, LR16YY, LR16YYY, LR16YYYY, LR16YYYYY, LR16YYYYYY, LR16YYYYYYY, LR16-Y, LR16-YY, LR16-YYY, LR16-YYYY, LR16-YYYYY, LR16-YYYYYY, LR16-YYYYYYY	
DIRECTV Manufacturer Code:300	R16, R16-300, R16Y, R16YY, R16YYY, R16YYYY, R16YYYYY, R16YYYYYY, R16YYYYYYY, R16-Y, R16-YY, R16-YYY, R16-YYYY, R16-YYYYY, R16-YYYYYY, R16-YYYYYYY, LR16, LR16-300, LR16Y, LR16YY, LR16YYY, LR16YYYY, LR16YYYYY, LR16YYYYYY, LR16YYYYYYY, LR16-Y, LR16-YY, LR16-YYY, LR16-YYYY, LR16-YYYYY, LR16-YYYYYY, LR16-YYYYYYY	
DIRECTV MFR Code:300	R16, R16-300, R16Y, R16YY, R16YYY, R16YYYY, R16YYYYY, R16YYYYYY, R16YYYYYYY, R16-Y, R16-YY, R16-YYY, R16-YYYY, R16-YYYYY, R16-YYYYYY, R16-YYYYYYY, LR16, LR16-300, LR16Y, LR16YY, LR16YYY, LR16YYYY, LR16YYYYY, LR16YYYYYY, LR16YYYYYYY, LR16-Y, LR16-YY, LR16-YYY, LR16-YYYY, LR16-YYYYY, LR16-YYYYYY, LR16-YYYYYYY	
Philips	DSR8102/17, DSR8102Y, DSR8102YY, DSR8102YYY, DSR8102YYYY, DSR8102YYYYY, DSR8102YYYYYY	

Authorized Network Ports: $1300
Service Order Code: 9.0Y

A Copy of this certificate must be presented to U.S. customs when any foreign-made products identified above are imported into the U.S.