TUV Rheinland of North America, Inc.
North American Headquarters
Newtown, CT 06470

TUV Rheinland of North America

Telecommunications Certification Body Certificate

United States of America
Equipment Certification under
47 CFR Part 68
TIA-968-A + TIA-968-A-1 + TIA-968-A-2 + TIA-968-A-3
Connection of Terminal Equipment to the Telephone Network

Subject to the provisions of 47 CFR Part 68 rules and regulations, certification is hereby granted for the equipment listed below. Changes in model number(s) or trade name(s) or modifications to the network interface require amendment of certification. Each piece of equipment bearing the listed trade name(s) and model number(s) shall be labeled in accordance with the provisions of TIA/EIA/TSB168-A.

Telephone equipment containing radio-frequency circuitry may require additional authorization(s) to be issued by the Federal Communications Commission or designated TCB prior to marketing such equipment in the United States. Failure to obtain the required equipment authorizations may subject the registrant to fines and penalties provided for in table V, section 501 and 503 of the Communications Act of 1934, as amended.

Certification No.: US: 6NHMM00BLR15300 **TUV RNA File No.:** 30650850.001

Date Approved: April 18, 2006
Registrant: Philips France, 51 rue Carnot, B.P. 301, Suresnex, Cedex, 92156, France
Manufacturer Name: Contract Manufacturers for Philips France
Equipment Description: Integrated Analog Modem for Satellite Receiver
Nature of Application: Original
AC-REN: 00B
Connectors: RJ11C

Type of Equipment: Embedded Analog Modem

Trade Name(s):	**Model Number(s):**
DIRECTV	LR15
DIRECTV Manufacturer Code : 300	LR15
DIRECTV MFR Code : 300	LR15
DIRECTV	LR15A
DIRECTV Manufacturer Code : 300	LR15A
DIRECTV MFR Code : 300	LR15A
DIRECTV	LR15C
DIRECTV Manufacturer Code : 300	LR15C
DIRECTV MFR Code : 300	LR15C
Philips	DSR8401/44
Philips	DSR8401/55
Philips	DSR8401/77
Philips	DSR8401Y
Philips	DSR8401YY
Philips	DSR8401YYY
Philips	DSR8401YYYY
Philips	DSR8401YYYYY
Philips	DSR8401YYYYYY
Philips	DSR8401YYYYYYY
DIRECTV MFR Code : 300	LR15Y
DIRECTV MFR Code : 300	LR15YY
DIRECTV MFR Code : 300	LR15YYY
DIRECTV MFR Code : 300	LR15YYYY

Trade Name(s):	Model Number(s):
DIRECTV MFR Code : 300	LR15YYYYY
DIRECTV MFR Code : 300	LR15YYYYYY
DIRECTV MFR Code : 300	LR15YYYYYYY
DIRECTV MFR Code : 300	LR15YYYYYYYY
DIRECTV MFR Code : 300	LR15-Y
DIRECTV MFR Code : 300	LR15-YY
DIRECTV MFR Code : 300	LR15-YYY
DIRECTV MFR Code : 300	LR15-YYYY
DIRECTV MFR Code : 300	LR15-YYYYY
DIRECTV MFR Code : 300	LR15-YYYYYY
DIRECTV MFR Code : 300	LR15-YYYYYYY
DIRECTV MFR Code : 300	YLR15Y
DIRECTV MFR Code : 300	YLR15YY
DIRECTV MFR Code : 300	YLR15YYY
DIRECTV MFR Code : 300	YLR15YYYY
DIRECTV MFR Code : 300	YLR15YYYYY
DIRECTV MFR Code : 300	YLR15YYYYYY
DIRECTV MFR Code : 300	YLR15YYYYYYY
DIRECTV MFR Code : 300	YLR15YYYYYYYY
DIRECTV MFR Code : 300	YYLR15Y
DIRECTV MFR Code : 300	YYLR15YY
DIRECTV MFR Code : 300	YYLR15YYY
DIRECTV MFR Code : 300	YYLR15YYYY
DIRECTV MFR Code : 300	YYLR15YYYYY
DIRECTV MFR Code : 300	YYLR15YYYYYY
DIRECTV MFR Code : 300	YYLR15YYYYYYY
DIRECTV MFR Code : 300	YYLR15YYYYYYYY

Authorized Network Ports: **1**

Service Order Code:

6.0Y

A Copy of this certificate must be presented to U.S. customs when any foreign-made products identified above are imported into the U.S.