TUV Rheinland of North America, Inc.
TCB Program
Youngsville, NC 27596

TÜVRheinland®
Precisely Right.

# *Telecommunications Certification Body Certificate*

United States of America
Equipment Certification under

**47 CFR Part 68**
***TIA-968-A + TIA-968-A-1 + TIA-968-A-2 + TIA-968-A-3 + TIA-968-A-4***
Connection of Terminal Equipment to the Telephone Network

Subject to the provisions of 47 CFR Part 68 rules and regulations, certification is hereby granted for the equipment listed below. Changes in model number(s) or trade name(s) or modifications to the network interface require amendment of certification. Each piece of equipment bearing the listed trade name(s) and model number(s) shall be labeled in accordance with the provisions of TIA/EIA/TSB168-A.

Telephone equipment containing radio-frequency circuitry may require additional authorization(s) to be issued by the Federal Communications Commission or designated TCB prior to marketing such equipment in the United States. Failure to obtain the required equipment authorizations may subject the registrant to fines and penalties provided for in table V, section 501 and 503 of the Communications Act of 1934, as amended.

**Certification No.:** **US: BBPFA03B06005** **TUVRheinland File:** 30751595.001

**Date Approved:** June 7, 2007
**Registrant:** RICOH COMPANY, LTD., 810 Shimo-imaizumi, Ebina , Kanagawa, 243-0460, Japan
**Manufacturer Name:** Ricoh Elemex (Shenzhen) Co., Ltd., Haoye Road, Fuyong town, Baoan District Shenzhen, Guangdong, 518103, China
**Equipment Description:** Desktop G3 Facsimile Transceiver
**Nature of Application:** Original
**AC-REN:** 0.3B
**Connectors:** RJ-11

**Type of Equipment:** Fax Modem

| Trade Name(s): | Model Number(s): | Certificates Affected: |
|---|---|---|
| Lanier | GX 3000SF | US: BBPFA03B06005 |
| Savin | GX 3000SF | US: BBPFA03B06005 |
| Lanier | GX 3050SFN | US: BBPFA03B06005 |
| Savin | GX 3050SFN | US: BBPFA03B06005 |
| Ricoh Aficio | GX 3000SF | US: BBPFA03B06005 |
| Ricoh Aficio | GX 3050SFN | US: BBPFA03B06005 |

**Authorized Network Ports:** P2
**Service Order Code:** 9.0Y

A Copy of this certificate must be presented to U.S. customs when any foreign-made products identified above are imported into the U.S.