TUV Rheinland of North America, Inc.
TCB Program
Youngsville, NC 27596

TÜVRheinland®
Precisely Right.

Telecommunications Certification Body Certificate

United States of America
Equipment Certification under

47 CFR Part 68
TIA-968-A + TIA-968-A-1 + TIA-968-A-2 + TIA-968-A-3 + TIA-968-A-4 and TIA-1096
Connection of Terminal Equipment to the Telephone Network

Subject to the provisions of 47 CFR Part 68 rules and regulations, certification is hereby granted for the equipment listed below. Changes in model number(s) or trade name(s) or modifications to the network interface require amendment of certification. Each piece of equipment bearing the listed trade name(s) and model number(s) shall be labeled in accordance with the provisions of TIA/EIA/TSB168-A.

Telephone equipment containing radio-frequency circuitry may require additional authorization(s) to be issued by the Federal Communications Commission or designated TCB prior to marketing such equipment in the United States. Failure to obtain the required equipment authorizations may subject the registrant to fines and penalties provided for in table V, section 501 and 503 of the Communications Act of 1934, as amended.

Certification No.: **US:BBPFA01B07009** **TUVRheinland File:** 30753171.001

Date Approved: October 31, 2007
Registrant: RICOH COMPANY, LTD., 810 Shimo-imaizumi, Ebina, Kanagawa, 243-0460, Japan
Manufacturer Name: SHANGHAI RICOH DIGITAL EQUIPMENT CO., LTD., No.887, Jingang Road, Jinqiao Export Processing Zone, Pudong new area, Shanghai, China
Equipment Description: Desktop G3 Facsimile Transceiver
Nature of Application: Original
AC-REN: 01B
Connectors: RJ-11C

Type of Equipment: Desktop G3 facsimile

Trade Name(s):	Model Number(s):	Certificates Affected:
Ricoh	Aficio SP C221SF, Aficio SP C222SF	
Gestetner	SP C221SF, SP C222SF	
Lanier	SP C221SF, SP C222SF	
Savin	SP C221SF, SP C222SF	

Authorized Network Ports: $
Service Order Code: 9.0Y

A Copy of this certificate must be presented to U.S. customs when any foreign-made products identified above are imported into the U.S.