PART 68 EQUIPMENT TCB CERTIFICATE

Certification under Part 68, Connection of Terminal Equipment to the Telephone Network

The product listed below has been found to comply with the applicable requirements for terminal equipment in accordance with the current editions of Federal Communications Commission CFR 47 Part 68, TIA-968-A, TIA-968-A-1, TIA-968-A-2, TIA-968-A-3, TIA-968-A-4, TIA-968-A-5, TIA-1096-A and TIA-168-B as adopted by the Administrative Council for Terminal Attachments (ACTA), plus all addenda in effect as of the date the product was approved.

Product No. US:GXATE18BHT-2112

File Number: HK08120373-1 Date of Grant: January 12, 2009

Type of application: Notice of Change - Adding new models

Responsible Party: Hung Tat International (Hong Kong) Limited

Country of origin: China

Type of Equipment: **Single Line Loop Start DTMF/Pulse Switchable Telephone**

Trade Name(s)	Model Number(s)
HUNG TAT	HAC/VC HT-2701
HUNG TAT	HAC/VC HT-2801
HUNG TAT	HAC/VC HT-2901
HUNG TAT	HAC/VC HT-2112
HUNG TAT	HAC/VC HT-1601
HUNG TAT	HAC/VC HT-1602
HUNG TAT	HAC/VC HT-1603
HUNG TAT	HAC/VC HT-1620
HUNG TAT	HAC/VC HT-2601
HUNG TAT	HAC/VC HT-2602
HUNG TAT	HAC/VC HT-2603
HUNG TAT	HAC/VC HT-2702
HUNG TAT	HAC/VC HT-2703
HUNG TAT	HAC/VC HT-2802
HUNG TAT	HAC/VC HT-2803
HUNG TAT	HAC/VC HT-2902
HUNG TAT	HAC/VC HT-2903
HUNG TAT	HAC/VC HT-9902
HUNG TAT	HAC/VC HT-9903
HUNG TAT	HAC/VC HT-2102
HUNG TAT	HAC/VC HT-2105 **-new**
HUNG TAT	HAC/VC HT-1002
HUNG TAT	HAC/VC HT-501
HUNG TAT	HAC/VC HT-601
HUNG TAT	HAC/VC HT-602
HUNG TAT	HAC/VC HT-702
HUNG TAT	HAC/VC HT-802
HUNG TAT	HAC/VC HT-798 **-new**
HUNG TAT	HAC/VC HT-113 **-new**
HUNG TAT	HAC/VC HT-2663 **-new**
HUNG TAT	HAC/VC HT-328 **-new**
HUNG TAT	HAC/VC HT-3463 **-new**

HUNG TAT	HAC/VC HT-5583 **-new**
HUNG TAT	HAC/VC HT-5963 **-new**
HUNG TAT	HAC/VC HT-2963 **-new**
HUNG TAT	HAC/VC HT-3063 **-new**
HUNG TAT	HAC/VC HT-3363 **-new**
EMERSON	HAC/VC EM 2115
EMERSON	HAC/VC EM 2110
EMERSON	HAC/VC EM 2131
EMERSON	HAC/VC EM 2132
EMERSON	HAC/VC EM2116 **-new**
EMERSON	HAC/VC EM2116RW **-new**
EMERSON	HAC/VC EM2116XX **-new**
EMERSON	HAC/VC EM2240 **-new**
EMERSON	HAC/VC EM2248 **-new**
EMERSON	HAC/VC EM2115RW
EMERSON	HAC/VC EM2115R (xx)
EMERSON	HAC/VC EM2115 (xx)
SAKAR	HAC/VC 60468
SAKAR	HAC/VC 15597-TRU **-new**
SAKAR	HAC/VC HT-426CL **-new**
SAKAR	HAC/VC HT-756CL **-new**
SAKAR	HAC/VC HT-795CL **-new**
SAKAR	HAC/VC HT-526CL **-new**
SAKAR	HAC/VC HT-626CL **-new**
SAKAR	HAC/VC HT-926CL **-new**
CURTIS	HAC/VC T-1673
CURTIS	HAC/VC T-1675
CURTIS	HAC/VC ST-1770
CURTIS	HAC/VC T-1679
CURTIS	HAC/VC T-1870 **-new**
CURTIS	HAC/VC T-1877 **-new**
CURTIS	HAC/VC T-1896 **-new**
CURTIS	HAC/VC T-1952 **-new**
CURTIS	HAC/VC T-5192 **-new**
CURTIS	HAC/VC T-1850 **-new**
CURTIS	HAC/VC T-1852 **-new**
CURTIS	HAC/VC T-1878 **-new**
CURTIS	HAC/VC T-1879 **-new**
CURTIS	HAC/VC -1880 **-new**
SYLVANIA	HAC/VC ST-1770 **-new**
SYLVANIA	HAC/VC ST-1878 **-new**
SYLVANIA	HAC/VC ST-1879 **-new**
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CT502
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CTC511
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CT550
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CT551
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CT553
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CT554
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CTC601
CRAIG ELECTRONICS INT'L LIMITED	HAC/VC CT2112
Kash N Gold., Deer Park, New York	HAC/VC 000964
Kash N Gold., Deer Park, New York	HAC/VC 000971
Kash N Gold., Deer Park, New York	HAC/VC 029149
Kash N Gold., Deer Park, New York	HAC/VC 028654
Kash N Gold., Deer Park, New York	HAC/VC 028661
Kash N Gold., Deer Park, New York	HAC/VC 630024

Kash N Gold., Deer Park, New York	HAC/VC 630062
Kash N Gold., Deer Park, New York	HAC/VC 630079
Kash N Gold., Deer Park, New York	HAC/VC 630123
SOUTHERN TELECOM	HAC/VC TC 115
SOUTHERN TELECOM	HAC/VC TP-132
SOUTHERN TELECOM	HAC/VC DPH201 **-new**
SOUTHERN TELECOM	HAC/VC DP200 **-new**
SOUTHERN TELECOM	HAC/VC DP340 **-new**
SOUTHERN TELECOM	HAC/VC DP-240 **-new**
SOUTHERN TELECOM	HAC/VC SP-300 **-new**
MAGNETICS	HAC/VC ACT 330
MAGNETICS	HAC/VC ACT303
MAGNETICS	HAC/VC ACT-331 **-new**
MAGNETICS	HAC/VC ACT-332 **-new**
MAGNETICS	HAC/VC ACT-334 **-new**
MAGNETICS	HAC/VC ACT-338 **-new**
ACCENTA	HAC/VC ACT 330 **-new**
ACCENTA	HAC/VC ACT 303 **-new**
ACCENTA	HAC/VC ACT-331 **-new**
ACCENTA	HAC/VC ACT-332 **-new**
ACCENTA	HAC/VC ACT-334 **-new**
ACCENTA	HAC/VC ACT-338 **-new**
JWIN	HAC/VC JT-P33
JWIN	HAC/VC JT-P29
JWIN	HAC/VC JT-P77
JWIN	HAC/VC JT-P420 **-new**
JWIN	HAC/VC JT-P320 **-new**
JWIN	HAC/VC JT-P720 **-new**
JWIN	HAC/VC JT-P390 **-new**
JWIN	HAC/VC JT-P220 **-new**
JWIN	HAC/VC JT-P230 **-new**
JWIN	HAC/VC JT-P330 **-new**
JWIN	HAC/VC JT-P390 **-new**
JWIN	HAC/VC JT-P670 **-new**
PRECISION	HAC/VC PT012AV
PRECISION	HAC/VC PT012AVC **-new**
PRECISION	HAC/VC PT012 **-new**
PRECISION	HAC/VC PT016 **-new**
PRECISION	HAC/VC PT049 **-new**
PRECISION	HAC/VC PT022 **-new**
MODERNPHONE	HAC/VC TC-990 **-new**
SMOOTH TALK	HAC/VC TLO8002 **-new**
SMOOTH TALK	HAC/VC TLO8003 **-new**
SMOOTH TALK	HAC/VC TLO8001-1 **-new**
SMOOTH TALK	HAC/VC TLO8001-2 **-new**
SMOOTH TALK	HAC/VC 21006 **-new**
BELL PHONE	HAC/VC 58200 **-new**
NIPPON	HAC/VC NP9252 **-new**
ZENEX	HAC/VC ZN-TP5141 **-new**
ZENEX	HAC/VC ZN-TP5140 **-new**
ZENEX	HAC/VC ZN-TP5144 **-new**
ZENEX	HAC/VC ZN-TP5143 **-new**
PANACOM	HAC/VC PA-7250 **-new**
BOSTON	HAC/VC BT-2702 **-new**
BOSTON	HAC/VC BT-2102 **-new**
BOSTON	HAC/VC BT-9161 **-new**

BOSTON	HAC/VC BT-330 **-new**
AUDIO	HAC/VC RTP-619 **-new**
AUDIO	HAC/VC RTP-381 **-new**
MBR	HAC/VC PX-65036 **-new**
PACIFIC HK	HAC/VC T-1877 **-new**
PACIFIC HK	HAC/VC PT-017 **-new**
SPRINT	HAC/VC PH-492 **-new**
SPRINT	HAC/VC PH-491 **-new**
SPRINT	HAC/VC PH-490 **-new**
TEAM PRODUCT	HAC/VC SB2015 **-new**
UNINEX	HAC/VC TA 903 **-new**
UNINEX	HAC/VC TA-903 **-new**
UNINEX	HAC/VC TS-904 **-new**
WINDSOR	HAC/VC T-3019 **-new**
REIZEN	HAC/VC 9254552 **-new**
TELSTAR	HAC/VC PH-491 **-new**
D.S.S.	HAC/VC JT-P390 **-new**
TELEMAX COMMUNICATION	HAC/VC CP8816GR **-new**

AC REN: 1.8B DC REN: N/A Connectors: RJ11C
Authorized Network Port(s): N/A
Service Order Codes(s): N/A

Telephone equipment containing Radio-Frequency circuitry may require additional equipment authorization(s) to be issued by the Commission prior to marketing such equipment in the United States. Failure to obtain the required equipment authorizations, when required, may subject the registrant to fines and penalties provided for in Table V, Section 501 and 503 of the Communications Act of 1934, as amended.

Each piece of equipment bearing the bearing the listed trade name(s) and model number(s) listed above shall be labeled as specified in 47 C.F.R. Section 68.300(b) and TIA-168-B.

A copy of this certificate must be presented to U.S. Customs when any Foreign-Made Products identified herein are imported into the U.S.

The Telecommunication Certification Body listed below has been authorized by the FCC to issue this Equipment Certification. The equipment listed above has been shown to comply with the applicable Rules by the Responsible Party.

Name of TCB: Intertek Testing Services NA, Inc.
Address of TCB: 70 Codman Hill Road
Boxborough, MA 01719
Phone Number of TCB: 978-263-2662

Administrator e-mail: TCB_Admin@Intertek.com
Web site (URL) of TCB: www.etlsemko.com