PART 68 EQUIPMENT TCB CERTIFICATE

Certification under Part 68, Connection of Terminal Equipment to the Telephone Network

The product listed below has been found to comply with the applicable requirements for terminal equipment in accordance with the current editions of Federal Communications Commission CFR 47 Part 68, TIA-968-A, TIA-968-A-1, TIA-968-A-2, TIA-968-A-3, TIA-968-A-4, TIA-968-A-5, TIA-1096-A and TIA-168-B as adopted by the Administrative Council for Terminal Attachments (ACTA), plus all addenda in effect as of the date the product was approved.

Product No. US:GXATE23BHT-2608

File Number: HK08120376-1 Date of Grant: January 12, 2009

Type of application: Notice of Change - Adding new models

Responsible Party: Hung Tat International (Hong Kong) Limited

Country of origin: China

Type of Equipment: **Single Line Loop Start DTMF/Pulse Switchable Telephone with Caller ID feature**

Trade Name(s)	Model Number(s)
HUNG TAT	HAC/VC HT-2608
HUNG TAT	HAC/VC HT-2508
HUNG TAT	HAC/VC HT-2408
HUNG TAT	HAC/VC HT-2308
HUNG TAT	HAC/VC HT-2208
HUNG TAT	HAC/VC HT-2108
HUNG TAT	HAC/VC HT-1008
HUNG TAT	HAC/VC HT-2808 -new
HUNG TAT	HAC/VC HT-79 -new
HUNG TAT	HAC/VC HT-86
HUNG TAT	HAC/VC HT-96
HUNG TAT	HAC/VC HT-97
CURTIS	HAC/VC TID582
CURTIS	HAC/VC TID583
CURTIS	HAC/VC TID584
CURTIS	HAC/VC TID585
CURTIS	HAC/VC TID586
CURTIS	HAC/VC TID587
CURTIS	HAC/VC T901 -new
CURTIS	HAC/VC T902 -new
SYLVANIA	HAC/VC STID582
SYLVANIA	HAC/VC STID583
SYLVANIA	HAC/VC STID584
SYLVANIA	HAC/VC STID585
SYLVANIA	HAC/VC STID586
SYLVANIA	HAC/VC STID587
SYLVANIA	HAC/VC ST901 -new
SYLVANIA	HAC/VC ST902 -new
JWIN	HAC/VC JT-P77
JWIN	HAC/VC JT-P86
JWIN	HAC/VC JT-P87
JWIN	HAC/VC JT-P88

JWIN	HAC/VC JT-P96
JWIN	HAC/VC JT-P97
SAKAR	HAC/VC KT1500CL
SAKAR	HAC/VC KT1600CL
SAKAR	HAC/VC KT1700CL
SAKAR	HAC/VC KT1800CL
SAKAR	HAC/VC KT1900CL
EMERSON	HAC/VC EM2515
EMERSON	HAC/VC EM2540
EMERSON	HAC/VC EM2502
EMERSON	HAC/VC EM2516 -new
EMERSON	HAC/VC EM2517 -new
SOUTHERN TELECOM	HAC/VC TC-500
SOUTHERN TELECOM	HAC/VC TC-502
SOUTHERN TELECOM	HAC/VC TC-515
ACCENTA	HAC/VC ACT343 -new
ACCENTA	HAC/VC ACT301 -new
ACCENTA	HAC/VC ACT302 -new
ACCENTA	HAC/VC ACT303 -new
ACCENTA	HAC/VC ACT304 -new
ACCENTA	HAC/VC ACT305 -new
ACCENTA	HAC/VC ACT312 -new
ACCENTA	HAC/VC ACT313 -new
ACCENTA	HAC/VC ACT314 -new
ACCENTA	HAC/VC ACT315 -new
ACCENTA	HAC/VC ACT318 -new
ACCENTA	HAC/VC ACT321 -new
ACCENTA	HAC/VC ACT328 -new
ACCENTA	HAC/VC ACT330 -new
ACCENTA	HAC/VC ACT331 -new
ACCENTA	HAC/VC ACT332 -new
ACCENTA	HAC/VC ACT333 -new
ACCENTA	HAC/VC ACT334 -new
ACCENTA	HAC/VC ACT335 -new
ACCENTA	HAC/VC ACT336 -new
ACCENTA	HAC/VC ACT337 -new
ACCENTA	HAC/VC ACT338 -new
ACCENTA	HAC/VC ACT339 -new
ACCENTA	HAC/VC ACT340 -new
ACCENTA	HAC/VC ACT341 -new
ACCENTA	HAC/VC ACT342 -new
ACCENTA	HAC/VC ACT343 -new
ACCENTA	HAC/VC ACT344 -new
ACCENTA	HAC/VC ACT345 -new
MAGNETICS	HAC/VC ACT301 -new
MAGNETICS	HAC/VC ACT302 -new
MAGNETICS	HAC/VC ACT303 -new
MAGNETICS	HAC/VC ACT304 -new
MAGNETICS	HAC/VC ACT305 -new
MAGNETICS	HAC/VC ACT312 -new
MAGNETICS	HAC/VC ACT313 -new
MAGNETICS	HAC/VC ACT314 -new
MAGNETICS	HAC/VC ACT315 -new
MAGNETICS	HAC/VC ACT318 -new
MAGNETICS	HAC/VC ACT321 -new
MAGNETICS	HAC/VC ACT328 -new

MAGNETICS	HAC/VC ACT330 -new
MAGNETICS	HAC/VC ACT331 -new
MAGNETICS	HAC/VC ACT332 -new
MAGNETICS	HAC/VC ACT333 -new
MAGNETICS	HAC/VC ACT334 -new
MAGNETICS	HAC/VC ACT335 -new
MAGNETICS	HAC/VC ACT336 -new
MAGNETICS	HAC/VC ACT337 -new
MAGNETICS	HAC/VC ACT338 -new
MAGNETICS	HAC/VC ACT339 -new
MAGNETICS	HAC/VC ACT340 -new
MAGNETICS	HAC/VC ACT341 -new
MAGNETICS	HAC/VC ACT342 -new
MAGNETICS	HAC/VC ACT343 -new
MAGNETICS	HAC/VC ACT344 -new
MAGNETICS	HAC/VC ACT345 -new
CORTELCO	HAC/VC 615021V0E21M -new
ZENEX	HAC/VC ZN-TP5142 -new
BOSTON	HAC/VC BT-2608 -new
TELSTAR	HAC/VC PH-496 -new
TRISONIC	HAC/VC TS-TL799CD -new
CORA	HAC/VC CRT-6100 -new
CORA	HAC/VC CRT-5350 -new
HUNG TAT	HAC/VC HT-111 -new
HUNG TAT	HAC/VC HT-1608 -new
HUNG TAT	HAC/VC HT-1088 -new
HUNG TAT	HAC/VC HT-118 -new
HUNG TAT	HAC/VC HT-2188 -new
HUNG TAT	HAC/VC HT-2368 -new
HUNG TAT	HAC/VC HT-2668 -new
HUNG TAT	HAC/VC HT-2688 -new
HUNG TAT	HAC/VC HT-2968 -new
HUNG TAT	HAC/VC HT-3080 -new
HUNG TAT	HAC/VC HT-3088 -new
HUNG TAT	HAC/VC HT-3468 -new
HUNG TAT	HAC/VC HT-368 -new
HUNG TAT	HAC/VC HT-388 -new
HUNG TAT	HAC/VC HT-3968 -new
HUNG TAT	HAC/VC HT-330 -new
HUNG TAT	HAC/VC HT-430 -new
HUNG TAT	HAC/VC HT-450 -new
HUNG TAT	HAC/VC HT-530 -new
HUNG TAT	HAC/VC HT-630 -new
HUNG TAT	HAC/VC HT-5568 -new
HUNG TAT	HAC/VC HT-5588 -new
HUNG TAT	HAC/VC HT-5968 -new
HUNG TAT	HAC/VC HT-6168 -new
HUNG TAT	HAC/VC HT-6900 -new
HUNG TAT	HAC/VC HT-6968 -new
HUNG TAT	HAC/VC HT-7900 -new
HUNG TAT	HAC/VC HT-8088 -new
HUNG TAT	HAC/VC HT-9168 -new
HUNG TAT	HAC/VC HT-9188 -new
HUNG TAT	HAC/VC HT-968 -new
HUNG TAT	HAC/VC HT-6901 -new
HUNG TAT	HAC/VC HT-7901 -new

HUNG TAT	HAC/VC HT-5961 -new
HUNG TAT	HAC/VC HT-2961 -new
HUNG TAT	HAC/VC HT-6961 -new
HUNG TAT	HAC/VC HT-2661 -new
HUNG TAT	HAC/VC HT-5561 -new
CORA	HAC/VC CRT-3200 -new
CORA	HAC/VC CRT-4240 -new
CORA	HAC/VC CRT-7700 -new
CORA	HAC/VC CRT-7400 -new
CORA	HAC/VC CRT-8500 -new
CORA	HAC/VC CRT-9500 -new
CORTELCO	HAC/VC HT-3968 -new
CORTELCO	HAC/VC HT-3968CW -new
CORTELCO	HAC/VC HT-5568 -new
CORTELCO	HAC/VC HT-5568CW -new
CHATEAU	HAC/VC HT-6000 -new
CHATEAU	HAC/VC HT-8000 -new
CHATEAU	HAC/VC HT-8500 -new
CURTIS	HAC/VC TID991 -new
CURTIS	HAC/VC TID970 -new
SYLVANIA	HAC/VC STID991 -new
SYLVANIA	HAC/VC STID970 -new
SOUTHERN TELECOM	HAC/VC DP640 -new
SOUTHERN TELECOM	HAC/VC DP646 -new
SOUTHERN TELECOM	HAC/VC DP648 -new
EMERSON	HAC/VC EM2640 -new
EMERSON	HAC/VC EM2646 -new
EMERSON	HAC/VC EM2646CB -new
EMERSON	HAC/VC EM2647 -new
EMERSON	HAC/VC EM2746 -new
JWIN	HAC/VC JT-P330 -new
JWIN	HAC/VC JT-P430 -new
JWIN	HAC/VC JT-P530 -new
JWIN	HAC/VC JT-P531 -new
JWIN	HAC/VC JT-P590 -new
JWIN	HAC/VC JT-P630 -new
JWIN	HAC/VC JT-P730 -new
JWIN	HAC/VC JT-P830 -new
SAKAR	HAC/VC HT333ID -new
SAKAR	HAC/VC HT444ID -new
SAKAR	HAC/VC HT555ID -new
SAKAR	HAC/VC HT848CL -new
SAKAR	HAC/VC HT888CL -new
SAKAR	HAC/VC MAX64721 -new
MAGNETICS	HAC/VC ACT344 -new
MAGNETICS	HAC/VC ACT345 -new
MAGNETICS	HAC/VC ACT341 -new
MAGNETICS	HAC/VC ACT339 -new
ACCENTA	HAC/VC ACT344 -new
ACCENTA	HAC/VC ACT345 -new
ACCENTA	HAC/VC ACT341 -new
ACCENTA	HAC/VC ACT339 -new
H.R.S.	HAC/VC AMB5100 -new
H.R.S.	HAC/VC AMB5200 -new
H.R.S.	HAC/VC AMB5300 -new
H.R.S.	HAC/VC AMB5500 -new

H.R.S.	HAC/VC AMB5800 -new
PRECISION	HAC/VC CID200 -new
PRECISION	HAC/VC PT026 -new
BOSTON	HAC/VC BT-9161 -new
TELSTAR	HAC/VC PH-494 –new

AC REN: 2.3B DC REN: N/A Connectors: RJ11C
Authorized Network Port(s): N/A
Service Order Codes(s): N/A

Telephone equipment containing Radio-Frequency circuitry may require additional equipment authorization(s) to be issued by the Commission prior to marketing such equipment in the United States. Failure to obtain the required equipment authorizations, when required, may subject the registrant to fines and penalties provided for in Table V, Section 501 and 503 of the Communications Act of 1934, as amended.

Each piece of equipment bearing the bearing the listed trade name(s) and model number(s) listed above shall be labeled as specified in 47 C.F.R. Section 68.300(b) and TIA-168-B.

A copy of this certificate must be presented to U.S. Customs when any Foreign-Made Products identified herein are imported into the U.S.

The Telecommunication Certification Body listed below has been authorized by the FCC to issue this Equipment Certification. The equipment listed above has been shown to comply with the applicable Rules by the Responsible Party.

Name of TCB: Intertek Testing Services NA, Inc.
Address of TCB: 70 Codman Hill Road
Boxborough, MA 01719
Phone Number of TCB: 978-263-2662

Administrator e-mail: TCB_Admin@Intertek.com
Web site (URL) of TCB: www.etlsemko.com