Hewlett-Packard Company
153 Taylor Street
Littleton, MA 01460, USA
www.hp.com

Suppliers Declaration of Conformity

Place of issue: **153 Taylor Street, Littleton, MA 01460**
Date of issue: **22nd July 2011**

Hewlett-Packard Company located at 153 Taylor Street, Littleton, MA 01460 in the United States of America hereby certifies that the following H3C router products:

HP A-MSR30-60 is the H3C Router MSR30-60
Fitted with the following optional interface modules:

RT-SIC-1FXO (1 x PoTS Interface)
RT-SIC-2FXO (2 x PoTS Interface)
RT-SIC-1FXS (1 x PoTS Subscriber equipment Interface)
RT-SIC-2FXS (2 x PoTS Subscriber equipment Interface)
RT-SIC-1T1-F (1 x Fractional T1 Interface)
RT-SIC-1VT1 (1 x Voice T1 Interface)
RT-SIC-1ADSL (1 x ADSL2/2+ Interface)
RT-SIC-1BU (1 x ISDN Basic Rate U Interface)
RT-SIC-2FXS1FXO (2 x PoTS Subscriber equipment Interface + 1 x PoTS Interface)
RT-DSIC-4FXS1FXO (4 x PoTS Subscriber equipment Interface + 1 x PoTS Interface)
RT-DSIC-1SHDSL-8W (1 x G.SHDSL 8-wire interface)
RT-MIM-1VT1 (1 x Voice T1 Interface)
RT-MIM-2VT1 (2 x Voice T1 Interface)
RT-MIM-2T1 (2 x T1 interface)
RT-MIM-8T1 (8 x T1 interface)
RT-MIM-2T1-F (2 x Fractional T1 Interface)
RT-MIM-4T1-F (4 x Fractional T1 Interface)
RT-MIM-8T1-F (8 x Fractional T1 Interface)
RT-MIM-IMA-4T1 (4 x IMA T1 Interface)
RT-MIM-2FXO (2 x PoTS Interface)
RT-MIM-4FXO (4 x PoTS Interface)
RT-MIM-2FXS (2 x PoTS Subscriber equipment Interface)
RT-MIM-4FXS (4 x PoTS Subscriber equipment Interface)
RT-MIM-8FXS8FXO (8 x PoTS Subscriber equipment Interface + 8 x PoTS Interface)
RT-MIM-1G.SHDSL (1 x G.SHDSL Interface)
RT-MIM-1SHL-4W (1 x G.SHDSL Interface 4 wire)

Bearing labeling identification number US:3CMIS01BMSR3060 complies with the Federal Communications Commission's ("FCC") Rules and Regulations 47 CFR Part 68, and the Administrative Council on Terminal Attachments ("ACTA") adopted technical criteria **TIA-968-B, Telecommunications – Telephone Terminal Equipment – Technical Requirements for Connection of Terminal Equipment to the Telephone Network, August 11th 2009** plus **Errata for TIA-968-B, March 12th 2010** and **TIA-1096-A Telecommunications – Telephone Terminal Equipment – Connector Requirements for Connection of Terminal Equipment to the Telephone Network, March 17th 2008**

Chris Allen
Compliance Engineer, HP A-Series Routers

