GRANT OF EQUIPMENT AUTHORIZATION

TCB **Certification** TCB

Issued Under the Authority of
The
FEDERAL COMMUNICATIONS COMMISSION
By:

Bay Area Compliance Laboratories Corp.

1274 Anvilwood Avenue,
Sunnyvale, CA 94089, USA

PART 68 - EQUIPMENT AUTHORIZATION

EQUIPMENT AUTHORIZATION UNDER PART 68, CONNECTION OF TERMINAL EQUIPMENT TO THE TELEPHONE NETWORK SUBJECT TO THE PROVISIONS OF PART 68 OF THE COMMISSION'S RULES AND REGULATIONS AND TO TIA-968-B + TIA-1096 + TIA-1096-A, EQUIPMENT AUTHORIZATION IS HEREBY GRANTED FOR THE EQUIPMENT LISTED HEREIN. ANY CHANGE IN MODEL UNDER OR TRADE NAME REQUIRES AMENDMENT OF EQUIPMENT AUTHORIZATION. EACH PIECE OF EQUIPMENT BEARING THE LISTED TRADE NAME(S) AND MODEL NUMBER(S) SHALL BE LABELED IN ACCORDANCE WITH THE PROVISIONS OF SECTION 68.300 AND TSB 168.

TELEPHONE EQUIPMENT CONTAINING RADIO-FREQUENCY CIRCUITRY MAY REQUIRE ADDITIONAL, AUTHORIZATION(S) TO BE ISSUED BY THE COMMISSION PRIOR TO MARKETING SUCH EQUIPMENT IN THE UNITED STATES. FAILURE TO OBTAIN THE REQUIRED EQUIPMENT AUTHORIZATIONS, WHEN REQUIRED, MAY SUBJECT THE REGISTRANT TO FINES AND PENALTIES PROVIDED FOR IN TABLE V, SECTION 501 AND 503 OF THE COMMUNICATIONS ACT OF 1934, AS MENDED.

FUTURE CORRESPONDENCE CONCERNING THIS EQUIPMENT AUTHORIZATION SHOULD REFERENCE THE FILE NUMBER, THE REGISTRATION NUMBER AND DATE OF GRANT.

The product listed below, subject to the provision of C.F.R. 47 Part 68, has been found to comply with the rules of the Federal Communications Commission and Technical Requirements for Connection of Terminal Equipment to the Telephone Network, TIA-1096-A and TIA-968-B by the Telecommunication Certification Body as listed above.

Registration No.:	US: BKCXP00BBE112230			**File No.:**	S1207193
Date Granted:	2012-07-24				
Responsible Party:	Belkin International, Inc.			**RPC:**	BKC
U.S. Agent for Service:	Belkin International, Inc., 12054 East Waterfront Drive, Playa Vista, CA 90094, USA				
Equipment Description:	Power tap with surge protector, ancillary phone surge protector				
Nature of Application:	Family to a previously certified model				
AC-REN:	0.0B	**DC-REN:**	N/A	**Connector(s):**	RJ-11CW
Type of Equipment:	XP				
Trade Name:	Belkin	**Model Number:**	Please refer to Appendix A		
Registration Affected:	N/A				
Authorized Network Ports:	N/A				
Service Order Code:	N/A				

A COPY OF THIS EQUIPMENT AUTHORIZATION MUST BE PRESENTED TO THE U.S. CUSTOMS SERVICES WHEN ANY FOREIGN-MADE PRODUCTS IDENTIFIED HEREIN ARE IMPORTED INTO THE U.S.

Address:
Belkin International, Inc.
12054 East Waterfront Drive, Playa Vista, CA 90094,
USA

Appendix A–Model Number List

Trade Name	Model Numbers			
Belkin	7-20008	BE107202fc12	BE108231fc10	BE112232fc12
	958-431	BE108200-06	BE108231fc12	BE112234-08
	958-445	BE108200fc06	BE108231fc12-DP	BE112234-10
	AS21200-08-DP	BE108200fc08	BE108232fc06	BE112234-10-DP
	AS21200fc08-DP	BE108200fc10	BE108232fc08	BE112234-10-OD
	BE107200-06	BE108201fc06	BE108232fc10	BE112234-10-SN
	BE107200-12	BE108201fc08	BE108232fc12	BE112234fc06
	BE107200fc04	BE108201fc10	BE112230-08-OD	BE112234fc08
	BE107200fc05	BE108201fc12	BE112230-08-SN	BE112234fc10
	BE107200fc06	BE108202fc06	BE112230fc06	BE112234fc12
	BE107200fc08	BE108202fc08	BE112230fc08	BE112234sp10
	BE107200fc12	BE108202fc10	BE112230fc10	SSC-12036J
	BE107201fc04	BE108202fc12	BE112230fc12	SSC-7021J-US/CC
	BE107201fc05	BE108230-06	SSC-12O36J-CA	SSC-7025J-US/CC
	BE107201fc06	BE108230-12	BE112231-08	SSC-803KJ-US/CC
	BE107201fc08	BE108230fc06	BE112231fc06	BV**********
	BE107201fc08-DP	BE108230fc08	BE112231fc08	BV107********
	BE107201fc12	BE108230fc10	BE112231fc10	BV108********
	BE107202fc04	BE108230fc12	BE112231fc12	BV112********
	BE107202fc05	BE108231fc06	BE112232fc06	F5Z**********
	BE107202fc06	BE108200fc12	BE112232fc08	BS*****-***-***
	BE107202fc08	BE108231fc08	BE112232fc10	BV***************
	BE112230-08			

Note: Explanation of model designation BV**********, BV107********, BV108********, BV112********:
The client confirmed the " * " denotes 0-9, A-Z or blank and the new added BV model numbers are the same product as BE series we tested last time, just cosmetic look (colors and shape).

Explanation of model designation F5Z**********, BS*****-***-***, BV***************:
The client confirmed the " * " denotes 0-9, A-Z or " - " or blank.

Indemnification and Liability Statement

ACTA Secretariat
c/o ATIS
1200 G Street, NW
Suite 500
Washington, DC 20005

RE: Statement of Indemnification, Liability, and additional information about the Power Tap with Surge Protector, ancillary Phone surge protector US: BKCXP00BBE112230, ancillary phone surge protector, and see appendix for model number list.

ACTA Secretariat:


Belkin International, Inc. hereby indemnifies and holds harmless the Administrative Council for Terminal Attachment ("ACTA"), its members, affiliates, Secretariat, and Sponsors, and each of their officers, directors, employees, participants, agents and representatives (the "ACTA Parties"), of and from any and all liabilities, losses, costs, damages, claims, suits or expenses (including reasonable attorneys' fees and costs) of any kind whatsoever, arising from or relating to the Product, or ***Belkin International, Inc.*** Supplier's Declaration of Conformity ("SDoC") or Telecommunications Certification Body ("TCB") Grant of Certification submitted to ACTA in connection therewith.

Belkin International, Inc. hereby acknowledges and agrees that ACTA, and the ACTA Parties shall not, and do not, assume, and expressly disclaim, any and all liability, responsibility and obligation in connection with any loss, damage or claim arising from or relating to, in any way, ACTA's inactions or actions relating to publication, distribution or other use of any information relating to or concerning the Product, including without limitation in connection with any claims or liabilities sounding in contract, tort (including negligence or strict liability), or otherwise, and in no circumstances shall ACTA or the ACTA Parties be liable for any loss of profits, loss of use, loss of production, loss of goodwill, or incidental, direct, indirect or consequential damages of any kind.

Pursuant to §68.218 and §68.348 in the FCC Rules and Regulations, no changes will be made to the above referenced Product or its protective circuitry that would result in any change in the information contained in the corresponding SDoC or TCB Grant of Certification without filing of a new SDoC or TCB Grant of Certification.

<*Name of company officer*> James Huang

<*Function of officer*> Regulatory Compliance Engineer Jul. 12, 2012

<*Signature*> 

Model list:

7-20008	BE107202fc08	BE108200fc12	BE112232fc06
958-431	BE107202fc12	BE108231fc08	BE112232fc08
958-445	BE108200-06	BE108231fc10	BE112232fc10
AS21200-08-DP	BE108200fc06	BE108231fc12	BE112232fc12
AS21200fc08-DP	BE108200fc08	BE108231fc12-DP	BE112234-08
BE107200-06	BE108200fc10	BE108232fc06	BE112234-10
BE107200-12	BE108201fc06	BE108232fc08	BE112234-10-DP
BE107200fc04	BE108201fc08	BE108232fc10	BE112234-10-OD
BE107200fc05	BE108201fc10	BE108232fc12	BE112234-10-SN
BE107200fc06	BE108201fc12	BE112230-08-OD	BE112234fc06
BE107200fc08	BE108202fc06	BE112230-08-SN	BE112234fc08
BE107200fc12	BE108202fc08	BE112230fc06	BE112234fc10
BE107201fc04	BE108202fc10	BE112230fc08	BE112234fc12
BE107201fc05	BE108202fc12	BE112230fc10	BE112234sp10
BE107201fc06	BE108230-06	BE112230fc12	SSC-12036J
BE107201fc08	BE108230-12	SSC-12O36J-CA	SSC-7021J-US/CC
BE107201fc08-DP	BE108230fc06	BE112231-08	SSC-7025J-US/CC
BE107201fc12	BE108230fc08	BE112231fc06	SSC-803KJ-US/CC
BE107202fc04	BE108230fc10	BE112231fc08	BE107202fc05
BE108230fc12	BE112231fc10	BE107202fc06	BE108231fc06
BE112231fc12	BV**********	BV107********	BV112********
BV108********	F5Z**********	BS*****-***-***	BV***************