GRANT OF EQUIPMENT AUTHORIZATION

TCB **Certification** **TCB**

Issued Under the Authority of
The
FEDERAL COMMUNICATIONS COMMISSION
By:

Bay Area Compliance Laboratories Corp.

1274 Anvilwood Avenue,
Sunnyvale, CA 94089, USA

PART 68 - EQUIPMENT AUTHORIZATION

EQUIPMENT AUTHORIZATION UNDER PART 68, CONNECTION OF TERMINAL EQUIPMENT TO THE TELEPHONE NETWORK SUBJECT TO THE PROVISIONS OF PART 68 OF THE COMMISSION'S RULES AND REGULATIONS AND TO TIA-968-B + TIA-1096 + TIA-1096-A, EQUIPMENT AUTHORIZATION IS HEREBY GRANTED FOR THE EQUIPMENT LISTED HEREIN. ANY CHANGE IN MODEL UNDER OR TRADE NAME REQUIRES AMENDMENT OF EQUIPMENT AUTHORIZATION. EACH PIECE OF EQUIPMENT BEARING THE LISTED TRADE NAME(S) AND MODEL NUMBER(S) SHALL BE LABELED IN ACCORDANCE WITH THE PROVISIONS OF SECTION 68.300 AND TSB 168.

TELEPHONE EQUIPMENT CONTAINING RADIO-FREQUENCY CIRCUITRY MAY REQUIRE ADDITIONAL, AUTHORIZATION(S) TO BE ISSUED BY THE COMMISSION PRIOR TO MARKETING SUCH EQUIPMENT IN THE UNITED STATES. FAILURE TO OBTAIN THE REQUIRED EQUIPMENT AUTHORIZATIONS, WHEN REQUIRED, MAY SUBJECT THE REGISTRANT TO FINES AND PENALTIES PROVIDED FOR IN TABLE V, SECTION 501 AND 503 OF THE COMMUNICATIONS ACT OF 1934, AS MENDED.

FUTURE CORRESPONDENCE CONCERNING THIS EQUIPMENT AUTHORIZATION SHOULD REFERENCE THE FILE NUMBER, THE REGISTRATION NUMBER AND DATE OF GRANT.

The product listed below, subject to the provision of C.F.R. 47 Part 68, has been found to comply with the rules of the Federal Communications Commission and Technical Requirements for Connection of Terminal Equipment to the Telephone Network, TIA-1096-A and TIA-968-B by the Telecommunication Certification Body as listed above.

Registration No.:	US: DRADL01BV2760	**File No.:**	S1306076
Date Granted:	2013-06-18		
Responsible Party:	DrayTek Corp.	**RPC:**	DRA
U.S. Agent for Service:	ABP International, Inc. 13988 Diplomat Drive, Suite 180, Dallas, TX 75234, USA		
Equipment Description:	VDSL2 Firewall Router with WLAN/VoIP		
Nature of Application:	Original		
AC-REN:	0.1B	**DC-REN:** N/A	**Connector(s):** RJ-14C
Type of Equipment:	DL		
Trade Names:	DrayTek	**Model Numbers:**	Vigor2760Vn Vigor2760n Vigor2760
Registration Affected:	N/A		
Authorized Network Ports:	N/A		
Service Order Code:	9.0Y		

A COPY OF THIS EQUIPMENT AUTHORIZATION MUST BE PRESENTED TO THE U.S. CUSTOMS SERVICES WHEN ANY FOREIGN-MADE PRODUCTS IDENTIFIED HEREIN ARE IMPORTED INTO THE U.S.

Address:
DrayTek Corp.
No. 26, Fu-Shing Road, HuKou County, Hsin-Chu Industrial Park,
Hsin-Chu, 303, Taiwan

DrayTek

Indemnification and Liability Statement

Date **2013/6/03**

ACTA Secretariat
c/o ATIS
1200 G Street, NW
Suite 500 Washington, DC 20005

RE: Statement of Indemnification, Liability, and additional information about the

	VDSL2 Firewall Router with WLAN/VoIP
Trade Name:	**DrayTek**
Model number:	**Vigor2760Vn / Vigor2760n / Vigor2760**
Reg. No.:	**US: DRADL01BV2760**

ACTA Secretariat:

< ***DrayTek Corp.*** > hereby indemnifies and holds harmless the Administrative Council for Terminal Attachment ("ACTA"), its members, affiliates, Secretariat, and Sponsors, and each of their officers, directors, employees, participants, agents and representatives (the "ACTA Parties"), of and from any and all liabilities, losses, costs, damages, claims, suits or expenses (including reasonable attorneys' fees and costs) of any kind whatsoever, arising from or relating to the Product, or < ***DrayTek Corp.*** > or Telecommunications Certification Body ("TCB") Grant of Certification submitted to ACTA in connection therewith.

< ***DrayTek Corp.*** > hereby acknowledges and agrees that ACTA, and the ACTA Parties shall not, and do not, assume, and expressly disclaim, any and all liability, responsibility and obligation in connection with any loss, damage or claim arising from or relating to, in any way, ACTA's inactions or actions relating to publication, distribution or other use of any information relating to or concerning the Product, including without limitation in connection with any claims or liabilities sounding in contract, tort (including negligence or strict liability), or otherwise, and in no circumstances shall ACTA or the ACTA Parties be liable for any loss of profits, loss of use, loss of production, loss of goodwill, or incidental, direct, indirect or consequential damages of any kind.

Pursuant to §68.218 and §68.348 in the FCC Rules and Regulations, no changes will be made to the above referenced Product or its protective circuitry that would result in any change in the information contained in the corresponding TCB Grant of Certification **US: DRADL01BV2760** *without* filing of TCB Grant of Certification.

Name of company officer ***Mr. Abbott Yu***
Function of officer ***Director***

Signature

DrayTek Corp.
No. 26, Fu-Shing Road, HuKou County, Hsin-Chu Industrial Park, Hsin-Chu, 303, Taiwan
886-3-597-2727
http://www.draytek.com.tw/index.php?lang=en