Grant of Equipment Authorization

Issued Under the Authority of the
FEDERAL COMMUNICATIONS COMMISSION
by
Nemko Canada, Inc.
303 River Road, Ottawa, Ontario, K1V 1H2, Canada

Certification number : **US: TPLDL01BD7V1** **Certificate number:** 7-7344

Date Approved:	October 23, 2014
Responsible Party:	TP-LINK TECHNOLOGIES CO., LTD.
U.S. Agent for Service:	TP-LINK USA CORPORATION
Equipment Description:	AC1750 Wireless Dual Band Gigabit ADSL2+ Modem Router
Filing Status:	Original

AC REN: 0.1B **Connectors:** RJ11C

Specifications: 47 CFR Part 68, TIA-968-B, TIA-968-B-1, TIA-1096-A

Type of Equipment: DL – DSL Modem

TRADE NAME	**MODEL NUMBER**
TP-LINK	Archer D7

Authorized Network Ports: N/A

Service Order Codes: N/A

REGISTRATION UNDER PART 68, CONNECTION OF TERMINAL EQUIPMENT TO THE TELEPHONE NETWORK

SUBJECT TO THE PROVISIONS OF PART 68 OF THE COMMISSION'S RULES AND REGULATIONS, REGISTRATION IS HEREBY GRANTED FOR THE EQUIPMENT LISTED HEREIN. ANY CHANGE IN MODEL NUMBER OR TRADE NAME REQUIRES AMENDMENT OF REGISTRATION. EACH PIECE OF EQUIPMENT BEARING THE LISTED TRADE NAME(S) AND MODEL NUMBER(S) SHALL BE LABELLED IN ACCORDANCE WITH THE PROVISIONS OF SECTION 68.300 OF THE COMMISSION'S RULES AND TIA-TSB168

TELEPHONE EQUIPMENT CONTAINING RADIO-FREQUENCY CIRCUITRY MAY REQUIRE ADDITIONAL AUTHORIZATION(S) TO BE ISSUED BY THE COMMISSION PRIOR TO MARKETING SUCH EQUIPMENT IN THE UNITED STATES. FAILURE TO OBTAIN THE REQUIRED EQUIPMENT AUTHORIZATIONS, WHEN REQUIRED, MAY SUBJECT THE REGISTRANT TO FINES AND PENALTIES PROVIDED FOR IN TABLE V, SECTION 501 AND 503 OF THE COMMUNICATIONS ACT OF 1934, AS AMENDED.

FUTURE CORRESPONDENCE CONCERNING THIS GRANT SHOULD REFERENCE THE REGISTRATION NUMBER, THE DATE OF GRANT AND THE CERTIFICATE NUMBER

ALL PRODUCTS LISTED ABOVE SHALL BE LABELLED AS SPECIFIED IN 47 CFR SECTION 68.300

A COPY OF THIS CERTIFICATE MUST BE PRESENTED TO U.S CUSTOMS WHEN ANY FOREIGN-MADE PRODUCTS IDENTIFIED HEREIN ARE IMPORTED INTO THE U.S

Nemko Canada, Inc.
303 River Road, Ottawa, Ontario K1V1H2, CANADA
tel +1 613 737 9680 fax +1 613 737 9691