PART 68 EQUIPMENT REGISTRATIONS

Issued Under the Authority of the

Federal Communications Commission

Washington, DC 20554

REGISTRATION UNDER PART 68, CONNECTION OF TERMINAL EQUIPMENT TO THE TELEPHONE NETWORK

Subject to the provisions of CFR 47 Part 68 of the commission's rules and regulations and TIA-968-B + TIA-968-B-1 + TIA-968-B-2 + TIA-968-B-3 + TIA-1096-A adopted by ACTA's technical requirements, registration is hereby granted for the equipment listed herein. Any change in model number or trade name requires amendment of certifications. Each piece of equipment bearing the listed trade name(s) and model number(s) shall be labelled in accordance with the provisions of 47 CFR sections 68.300 and TIA-168-B.

Telephone equipment containing radio-frequency circuitry may require additional, authorization to be issued by the commission prior to marketing such equipment in the United States. Failure to obtain the required equipment authorizations when required may subject the registrant to fines and penalties provided for in table V, section 501 and 503 of the communications act of 1934, as amended.

Future correspondence concerning this grant should reference the file number, the registration number, the date of grant, and the certificate number:

Certificate Holder:	DrayTek Corp.		
Address:	No. 26, Fu-Shing Rd., HuKou County, Hsin-Chu Industrial Park, Hsin-Chu, 303 TAIWAN		
Registration No.:	US: DRADL01AV2762	File No.:	SC18020101-DTC-001
Date Granted:	February 7, 2018		
Registrant:	DrayTek Corp.	RPC:	DRA
U.S. Product Information Contact:	ABP International, Inc.		
Equipment Description:	ADSL2/2+ & VDSL2 Router		
Nature of Application:	Original		
AC-REN:	0.1A		
DC-REN:	N/A		
Connector:	RJ-11		
Type of Equipment:	DL – x DSL Modem		
Trade Name:	DrayTek		
Model Number:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762V, Vigor2762Vn, Vigor2762Vac, Vigor2762e, Vigor2762ne, Vigor2762ace, Vigor2762Ve, Vigor2762Vne, Vigor2762Vace		
Registration Affected:	N/A		
Authorized Network Ports:	N/A		
Service Order Code:	N/A		

All products listed above must be labelled as specified in 47 CFR Section 68.300 and TIA-168-C.

A copy of this certificate must be presented to the US. Customs Services when any foreign-made products identified herein are imported into the U.S

Signature:

Leslie Bai
Director of Certification

SIEMIC
A Bureau Veritas Group Company

Issue Date: February 7, 2018

775 Montague Expressway, Milpitas, CA 95035, USA
Tel: 408 526 1188, Fax: 408 526 1088
Website: www.siemic.com, Email: info@siemic.com
Please check the validation of this certificate at http://www.siemic.com/Pages/siemic_db/public/certverification.asp