United States of America
FEDERAL COMMUNICATIONS COMMISSION

PART 68 – EQUIPMENT REGISTRATION

TCB

Issued Under the Authority of the
FEDERAL COMMUNICATIONS COMMISSION
Washington, DC 20554

TCB

By:
Bay Area Compliance Laboratory Corp.
230 Commercial St.
Sunnyvale, CA 94085

REGISTRATION UNDER PART 68, CONNECTION OF TERMINAL EQUIPMENT TO THE TELEPHONE NETWORK

SUBJECT TO THE PROVISIONS OF PART 68 OF THE COMMISSION'S RULES AND REGULATIONS ADOPTED BY ACTA'S TECHNICAL REQUIREMENTS, REGISTRATION IS HEREBY GRANTED FOR THE EQUIPMENT LISTED HEREIN. ANY CHANGE IN MODEL UNDER OR TRADE NAME REQUIRES AMENDMENT OF REGISTRATION. EACH PIECE OF EQUIPMENT BEARING THE LISTED TRADE NAME(S) AND MODEL NUMBER(S) SHALL BE LABELED IN ACCORDANCE WITH THE PROVISIONS OF SECTION 68.300.

TELEPHONE EQUIPMENT CONTAINING RADIO-FREQUENCY CIRCUITRY MAY REQUIRE ADDITIONAL, AUTHORIZATION(S) TO BE ISSUED BY THE COMMISSION PRIOR TO MARKETING SUCH EQUIPMENT IN THE UNITED STATES. FAILURE TO OBTAIN THE REQUIRED EQUIPMENT AUTHORIZATIONS, WHEN REQUIRED, MAY SUBJECT THE REGISTRANT TO FINES AND PENALTIES PROVIDED FOR IN TABLE V, SECTION 501 AND 503 OF THE COMMUNICATIONS ACT OF 1934, AS MENDED.

FUTURE CORRESPONDENCE CONCERNING THIS GRANT SHOULD REFERENCE THE FILE NUMBER, THE REGISTRATION NUMBER AND DATE OF GRANT:

Registration No.:	US: 5F4WT03B650D			**File No.:**	B0201163
Date Granted:	01/23/2002				
Registrant:	Lelux Electronics Ltd.				
Manufacturer Name:	Dongguan Lelux Electronics Co., Ltd				
Equipment Description:	Single Line 46/49MHz Cordless Telephone				
Nature of Application:	Original				
AC-REN:	0.3 B	**DC-REN:**	N/A	**Connector:**	RJ11C
Type of Equipment:	Conventional 43/49 MHz Cordless Phones				

Trade Name	**Model No.**	**Registration Affected**
Lelux	D HAC/VC 650D	

Authorized Network Ports:

Service Order Code:

ALL PRODUCTS LISTED ABOVE MUST BE LABELED AS SPECIFIED IN 47 C.F.R. SEC. 68.300.

A COPY OF THIS CERTIFICATE MUST BE PRESENTED TO THE U.S. CUSTOMS SERVICES WHEN ANY FOREIGN-MADE PRODUCTS IDENTIFIED HEREIN ARE IMPORTED INTO THE U.S.

Wednesday, January 23, 2002

Address:

Intertek Testing Services HK Ltd.
2/F., Garment Center, 576 Castle Peak Road,
Hong Kong, China