SUPPLIER'S DECLARATION OF CONFORMITY

Cisco Systems, Inc.
170 West Tasman Drive,
San Jose, CA 95134
USA

Declare under sole responsibility that the product(s),

MGX8850

bearing labeling identification number 5B1-USA-27520-XD-N comply(ies) with the Federal Communications Commission's ("FCC") Rules and Regulations 47 CFR Part 68, and the Administrative Council for Terminal Attachments ("ACTA") adopted technical criteria:

TIA/EIA/IS-968, July 2001	**Technical Criteria for Terminal Equipment to Prevent Harms to the Telephone Network**

Interface cards: AXSM-32-T1E1-E, RBBN-16-T1E1, PXM1E-16-T1E1

Place Of Issue : San Jose, CA
Date Of Issue : 09-19-02
Signature :



Hung Pham
Mgr, MSSBU Hardware Development

Indemnification And Liability Statement

Date : September 19, 2002
ACTA Secretariat
c/o ATIS
1200 G Street, NW
Suite 500
Washington, DC 20005

RE: Statement of Indemnification, Liability, and additional information about the MGX8850, 5B1-USA-27520-XD-N

ACTA Secretariat:
Cisco Systems, Inc. hereby indemnifies and holds harmless the Administrative Council for Terminal Attachment ("ACTA"), its members, affiliates, Secretariat, and Sponsors, and each of their officers, directors, employees, participants, agents and representatives (the "ACTA Parties"), of and from any and all liabilities, losses, costs, damages, claims, suits or expenses (including reasonable attorneys' fees and costs) of any kind whatsoever, arising from or relating to the above-referenced Product or Cisco Systems, Inc. Supplier's Declaration of Conformity ("SDoC") submitted to ACTA in connection therewith.

Cisco Systems, Inc.hereby acknowledges and agrees that ACTA, and the ACTA Parties shall not, and do not, assume, and expressly disclaim, any and all liability, responsibility and obligation in connection with any loss, damage or claim arising from or relating to, in any way, ACTA's publication, distribution or other use of any information relating to or concerning the Product, including without limitation in connection with any claims or liabilities sounding in contract, tort (including negligence or strict liability), or otherwise, and in no circumstances shall ACTA or the ACTA Parties be liable for any loss of profits, loss of use, loss of production, loss of goodwill, or incidental, direct, indirect or consequential damages of any kind.

Pursuant to §68.348 of the FCC Rules and Regulations, no changes will be made to the above referenced Product or its protective circuitry that would result in any change in the information contained in the corresponding SDoC #5B1-USA-27520-XD-N without filing of a new SDoC.
As specified in §68.324 (e)(3), a copy of the SDoC is freely available to the general public, and accessible to the disabled community, on the company website at http://www.cisco.com/

Signature :



Hung Pham
Mgr, MSSBU Hardware Development