United States of America
FEDERAL COMMUNICATIONS COMMISSION

GRANT OF FCC EQUIPMENT CERTIFICATION

TCB Issued Under the Authority of the **FEDERAL COMMUNICATIONS COMMISSION** **TCB**

By:
Communication Certification Laboratory
1940 West Alexander Street
Salt Lake City, UT 84119-2039

CERTIFICATION UNDER CFR 47 PART 68 - CONNECTION OF TERMINAL EQUIPMENT TO THE TELEPHONE NETWORK

SUBJECT TO THE PROVISIONS OF PART 68 STANDARD OF THE FCC RULES AND REGULATIONS, CERTIFICATION IS HEREBY GRANTED FOR THE EQUIPMENT LISTED HEREIN. ANY CHANGE IN MODEL NUMBER OR TRADE NAME REQUIRES AMENDMENT OF CERTIFICATION. EACH PIECE OF EQUIPMENT BEARING THE LISTED TRADE NAME(S) AND MODEL NUMBER(S) SHALL BE LABELED IN ACCORDANCE WITH THE PROVISIONS OF SECTION TSB168.

TELEPHONE EQUIPMENT CONTAINING RADIO-FREQUENCY CIRCUITRY MAY REQUIRE ADDITIONAL, AUTHORIZATION(S) TO BE ISSUED BY THE COMMISSION PRIOR TO MARKETING SUCH EQUIPMENT IN THE UNITED STATES. FAILURE TO OBTAIN THE REQUIRED EQUIPMENT AUTHORIZATIONS MAY SUBJECT THE RESPONSIBLE PARTY TO FINES AND PENALTIES PROVIDED FOR IN TABLE V, SECTION 501 AND 503 OF THE COMMUNICATIONS ACT OF 1934, AS AMENDED.

FUTURE CORRESPONDENCE CONCERNING THIS GRANT SHOULD REFERENCE THE FILE NUMBER, THE CERTIFICATION NUMBER AND DATE OF GRANT

Certification No **E3XISR-71142-MF-E** **File No:** 31-0716/63-0004

Date Granted: 10/2/03
Responsible Party: TADIRAN TELECOM INC.
Manufacturer Name: TADIRAN TELECOM BUSINESS SYSTEMS LTD.
Equipment Description: HYBRID KEY TELEPHONE SYSTEM PROVIDING UP TO 6000 TRADITIONAL AND VOIP PORTS
Nature of Filing MODIFICATION - ADDING FOUR NEW SYSTEM MODELS AND SOME NEW EQUIPMENT
AC-REN: 0.8B(ac) **DC-REN:** N/A **Connectors:** RJ21X,RJ2EX,RJ2FX,RJ2GX,RJ2HX, RJ48S,
Type of Equipment: MF - FULLY PROTECTED MULTIFUNCTION SYSTEMS

Trade Name	*Model No.*	*Certifications Affected*
TADIRAN TELECOM	IPx 4000	E3XISR-71142-MF-E
TADIRAN TELECOM	IPx 3000	E3XISR-71142-MF-E
TADIRAN TELECOM	IPx 800	E3XISR-71142-MF-E
TADIRAN TELECOM	IPx 500	E3XISR-71142-MF-E

Authorized Network Ports: 02LS2,02GS2,02RV2-T,TL31M,TL32M,TL11M,TL12M,02IS5,OL13C,04DU9-BN,04DU9-DN,04DU9-1KN,04DU9-1SN
Service Order Code: 9.0F, 6.0P

ALL PRODUCTS LISTED ABOVE MUST BE LABELED AS SPECIFIED IN TSB168.

A COPY OF THIS CERTIFICATE MUST BE PRESENTED TO THE U.S. CUSTOMS SERVICES WHEN ANY FOREIGN-MADE PRODUCTS IDENTIFIED HEREIN ARE IMPORTED INTO THE U.S.

RESPONSIBLE PARTY CONTACT:

Mr. Gabi Ayalon
TADIRAN TELECOM INC.
4 Tri Harbor
Port Washington, NY 11050

CCL Form 48